VISIBLE EIVIISSION NOTATIONS	,				
Inspector: Chema	Sauced				
Date of Inspection:	15			•	
Shift: 1st Shift or and Shift	Time:	GAM			
	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Commer	nts	
Visible Emission From Shaker	Nound				,
Visible Emission From Discharge Conveyor System	Noemal				

Normal means emissions prevailing or expected to prevail 80% of time process in operation, not counting start up ro shut down

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

Visible Emission From Discharge	Visible Emission From Shaker Machael	<u>ABNORMAL</u>	<u>NORMAL</u>	Unit Visual		ft Time:	Date of Inspection: /) // <- // <-	Inspector: Jaime M GORCIA	VISIBLE EMISSION NOTATIONS
	*** Committee of the Co				Comments				

Normal means emissions prevailing or expected to prevail 80% of time process in operation, not counting start up ro shut down

Conveyor System

- cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal. Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and
- characteristics of normal visible emissions for that specific process. or usual manner of operation and emission apperance. Failure to take steps or restore the operations is a diviation from the permit. If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

Inspector: Date of Inspection:

hift: 1st Shift or 2nd Shift Time:

	-1,	UD am			
unit.	Visual		Comm	ents	and the state of t
	Inspection -				
	<u>NORMAL</u>				
	or _			1905. 1905.	
	<u>ABNORMAL</u>				uus saara saar
Visible Emission From Shaker	<u> </u>				
	Modma				
Visible Emission From Discharge	***				
Conveyor System	Nobland				

Normal means emissions prevailing or expected to prevail 80% of time process in operation, not counting start up ro shut down

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission apperance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE EMISSION NOTATIONS					
Inspector: Autom Audio	M III				
Date of Inspection: 28 15					
Shift: 1st Shift or 2nd Shift	t Time:	500an			
	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Com Language Assertion L	ments	
Visible Emission From Shaker	Wormal				
Visible Emission From Discharge Conveyor System	Nomal				

Normal means emissions prevailing or expected to prevail 80% of time process in operation, not counting start up ro shut down

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission apperance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)